			oject: Cork CC Accessibility Audits	Job No: 027821	QTY	PHOTO REF		
LAUTING	Nontrinto			LOOATION	derr	THOTORE	ricolari	00010
		Use Type: Town Centre	Auditor: J Lowe	Date of Audit: 21/03/2008				
		Capita Ref: 014	Name: Tinahely	Address: Co. Wicklow				
Section 2:	Town PEDES	TRIAN CROSSING POINTS						
	REF: 2.1	QUESTION: Are th	nere suitable crossing points present a	t regular intervals to allow circulation thro	ughout th	e residential area	?	Y/N: No
303556	172949	An uncontrolled crossing is recomm side road and main road "T" junction paving exists. Any uncontrolled cross crossing point. It is a medium priorit other hand, the requirement to cross trying to get to the health centre.	n. No dropped kerbs nor tactile ssing should create a parallel ty as it is a quiet road but on the	Along Bridge Street towards the health centre.	1	21	3	€2,50
303691	173154	An uncontrolled crossing is recomm side road and main road "T" junction currently exists however the dropped Any uncontrolled crossing should cr	n. A dropped kerb on both sides ed kerbs are skewed with each other.	Along Main Street towards town centre.	1	2,3	3	€2,50
303765	173196	An uncontrolled crossing is recomm and straight road leading into Tinah paving exists. Any uncontrolled cros crossing point. It is a medium priorit other hand, the requirement to cros	ssing should create a parallel ty as it is a busy road but on the	Along Main Street.	1	1	3	€2,50
		There is no crossing point along the low levels of traffic were found on the for a lengthy distance. Consider pla length of this street at an appropriate	he day of the audit, high kerbs exists acing a crossing point along the	Top end of Main Street.	1	16	4	€2,50
	REF: 2.2	QUESTION: Are a	Il crossovers flush with the carriageway	y?				Y/N: Yes
	REF: 2.3	QUESTION: Is the	surface slip resistant?					Y/N: Yes
	REF: 2.4	QUESTION: Is blis	stered tactile paving present at all cross	sovers where the kerb upstand has been	removed	?		Y/N: Yes
	REF: 2.5	QUESTION: Is all	blistered paving located in a suitable m	nanner that will not lead to confusion for s	omeone	with a visual impa	irment?	Y/N: Yes

EASTING	NORTHING	RECOMMENDATION	LOCATION	QTY	PHOTO REF	PRIORITY	COS	TS
	<b>REF: 2.6</b>	<b>QUESTION:</b> Is all street furniture suitably located to ensu	ure that it will not cause a hazard t	o pedestrians?			Y/N:	Yes
	<b>REF</b> : 2.7	QUESTION: Is there a strong colour contrast at the kerb	edge to assist partially sighted us	ers?			Y/N:	Yes
Section 7:	Town HORIZ	ZONTAL CIRCULATION						
	REF: 7.1	<b>QUESTION:</b> Have guidance path surfaces been used sp	aringly to guide people around ob	stacles?			Y/N:	Yes
	REF: 7.2	<b>QUESTION:</b> Do the bars run in the direction of pedestria	n travel?				Y/N:	Yes
	REF: 7.3	<b>QUESTION:</b> Have information surfaces been used to dra points?	w attention to amenities such as p	phone kiosk, post	boxes, or inform	ation	Y/N:	Yes
	REF: 7.4	<b>QUESTION:</b> Are information surfaces level with the surro	ounding footway?				Y/N:	Yes
	REF: 7.5	QUESTION: Does the surface extend the full width of the	amenity or 800mm, whichever is	greater?			Y/N:	Yes
	REF: 7.6	QUESTION: Does a space of 400mm exist between the	amenity and surface?				Y/N:	Yes
	REF: 7.7	QUESTION: Are pedestrian routes free of hazards?					Y/N:	No
303469	173290	There are posts along the pedestrian path which require colour contrasting to highlight their presence. Reflective banding should also be considered for low level light conditions. Guidance on positioning and type can be found in section 5.3.3 "building for everyone" of the NDA.	Along Main Street.	4	15	3		€800
		Off street parking is a persistant problem at several locations within the town. Due to time of day variations and the audit being a snapshot an estimate of five locations has been included and this could be in the form of several solutions such as paint markings, high level signage restricting parking, bollards etc. Part of the solution should include secondary measures such as additional controlled parking, out of town parking connected with public transport and community education.	Throughout the town.	1	9	3		€5,000
		Throughout the town centre area, passage is severly interupted by the common occurrence of steps from residences out into the pedestrian walkway. In extreme cases, the passage is all but virtually blocked. In lesser cases, they are a hazard for persons with visual problems due to poor contrasting.	Througout the town	5	14,15,19	1		€3,000
	<b>REF: 7.8</b>	QUESTION: Does the lighting installation take into account	int the needs of people with visua	l impairments?			Y/N:	Yes

EASTING	NORTHING	RECOMMENDATION	LOCATION	QTY	PHOTO REF	PRIORITY	COSTS
	REF: 7.9	QUESTION: Are junctions between different surfaces sm confusion?	ooth to ensure that they do not present a	tripping h	azard or cause vis	sual	Y/N: Yes
	REF: 7.10	QUESTION: Are pedestrian routes a minimum of 1800m	m wide?				Y/N: Yes
	<b>REF</b> : 7.11	QUESTION: Is suitable seating provided at regular interv	als?				Y/N: No
		Along the main streets, there is generally a lack of suitable seating areas. A review of providing seats at regular intervals along main thoroughfares should take place. Following guidelines from section 5.3.7 of NDA "Building for Everyone".	Throughout town.	2		3	€3,000
	<b>REF:</b> 7.12	QUESTION: Is general circulation available to all areas b	y way of accessible routes?				Y/N: No
303628	173140	The southern area on the opposite of the island requires a continuation of passage by providing paved walkway and removal of two steps bounded by flower boxes. This will also improve the surface which is cracked.	Next to shops with Bar / wine merchant.	10m	6,7	2	€2,000
303666	173127	The area around the triangular stepped island in the town centre is difficult to access. Crossing is difficult due to high traffic loads, off street parking and lack of dropped kerbs with any form of controlled crossing. The area to access has public amenities such as library, court etc. It is highly recommended that crossing points are reviewed and that access is considered from various directions. In this instance due to the difficulties in crossing and high likelihood that persons will travel to this area a controlled crossing is recommended.	North and South access points over to the Triangular stepped island.	2	5,8,9	1	€15,000
303637	173105	Access to the library, seat, litter bin, noticeboard etc. on the island requires a few singular steps to be overcome. An entry/ exit crossing point at the same level of the library will help. The steps at the front would not need to be replaced but handrails, nosings etc need to be considered. The singular steps should have small ramped accesses put in place. Refer to 8.2	North side of triangular island.	3	9,10	1	€3,000
303622	173040	This area from the exit at the town centre upto the health centre has a series of poor paths / surfaces and steps. As such this entire street is needing considerable works and rather than treat every problem independently they have been summarised here. A montage of photos has been included. An immediate problem is that the paths either side of the road are poor in width with many kerbstones, steps and poles needing to be overcome. By concentrating on one side of the road, a path can be made accessible through widening without encroaching significantly into the roadspace. Other measures could be used such as one way traffic flows, chicanes, light signal control. A budgetry figure has been included but this may not be realistic depending on what measures are finally approved.	The length of bridge street up to the health centre.	200m	17,18,19,20,24, 25,26	, 1	€20,000

EASTING	NORTHING	RECOMMENDATION	LOCATION	QTY	PHOTO REF	PRIORITY	COS	TS
	REF: 7.13	QUESTION: Is town centre signage suitably positioned, s background? Is there alternative pictorial sig		contrast betw	veen letters and		Y/N:	Yes
Section 8:	Town VERTI	CAL CIRCULATION						
	REF: 8.1	QUESTION: Is the location of any steps clearly indicated	by use signage/colour contract/textur	e/lighting?			Y/N:	No
303691	173144	A series of steps (four, over a spilt level of one and three) exist which have no nosings, indications or handrails. Similarly no alternative method to pass through this area exists particularly for wheelchairs and a ramp or alternative crossing sould be considered. IN this instance a road chicane could serve to allow a pedestrian bypass.	Along Main Street towards town centre.	1	4	1		€5,000
303691	173155	Opposite the series of four steps on the other side of the road are two steps which blocks wheelchair access. These two steps should be changed to allow an alternative ramp over half their length, installing appropriate nosings and handrails or more sensibly the steps could be removed a long low gradient put in place.	Along Main Street towards town centre	1	2,3	2		€3,000
	REF: 8.2	QUESTION: Do any steps have a handrail to both side(s)	and does it extend 300mm beyond t	ne top and bo	ttom of any flight	?	Y/N:	No
303637	173106	The steps require nosings, corduroy tactile paving and handrails at appropriate intervals to help persons in ascending /descending.	Steps at front of triangular island.	3	10	3		€4,500
	REF: 8.3	<b>QUESTION:</b> Is any level change clearly lit?					Y/N:	Yes
	REF: 8.4	<b>QUESTION:</b> Are treads and risers uniform?					Y/N:	Yes
	REF: 8.5	<b>QUESTION:</b> Are nosings identifiable?					Y/N:	Yes
	REF: 8.6	QUESTION: Is the location of any ramp clearly indicated	by use signage/colour contract/textur	e/lighting?			Y/N:	Yes
	REF: 8.7	QUESTION: Are steps available as an alternative to any i	ramp or ramped surface?				Y/N:	Yes
	REF: 8.8	QUESTION: Have all ramps got a suitable gradient in res	pect to their length?				Y/N:	Yes
	REF: 8.9	QUESTION: Do any ramps have a handrail to both side(s	and does it extend 300mm beyond	the top and b	ottom of any fligh	t?	Y/N·	Yes

EASTING	NORTHING	RECOMMENDATION	LOCATION	QTY	PHOTO REF	PRIORITY	COSTS

Section 9:	Town INFO	RMATION		
	REF: 9.1	QUESTION: Is there a tactile plan of the town centre?	Y/N:	No
		Tactile information at key areas should be considered throughout the town.		
	REF: 9.2	<b>QUESTION:</b> If orientation information is available to the public, is it available in alternative formats?	Y/N:	Yes
	REF: 9.3	QUESTION: Are all relevant locations clearly signed?	Y/N:	No
		There is no signage to identify entrances, recommended routes, amenities etc. A review of pedestrian traffic throughout the area and hence a corresponding requirement for signage should take place. The provision of any signage needs to take into account requirements for persons of various disabilities. This could include braille signage. Any visual signage should have a text height of a minimum of 60mm, the background of the signboard should be white and the text should be black or blue.		
	REF: 9.4	QUESTION: Does the signage system incorporate colour/tone/ contrast and upper and lower case lettering?	Y/N:	Yes
Section 10:	Town Car P	arking		
	REF: 10.1	QUESTION: If required, are there any accessible parking spaces provided?	Y/N:	Yes
	REF: 10.2	<b>QUESTION:</b> Are on street accessible bays provided in a safe location?	Y/N:	Yes
	REF: 10.3	QUESTION: Does the accessible bay have a drop kerb to the rear to allow disabled motorists access to the walkway?	Y/N:	Yes
	REF: 10.4	QUESTION: Is the accessible car parking surface even and free from loose stones?	Y/N:	Yes
	REF: 10.5	QUESTION: Are accessible bays adequately lit?	Y/N:	Yes
	REF: 10.6	QUESTION: Are accessible bays adequately signed?	Y/N:	No
303636	173096	No high level signage for the disabled bay is in situ. The bay is well displayed in blue road markings making high level signage of a lower priority however it should not be discarded as it is an important feature for persons driving past to quickly ascertain that an accessable bay exists.		€240

EASTING	NORTHING	RECOMMENDATION	LOCATION	QTY	PHOTO REF	PRIORITY	COSTS
303661	173101	No high level signage for the disabled bay is in situ. The bay is well displayed in blue road markings making high level signage of a lower priority however it should not be discarded as it is an important feature for persons driving past to quickly ascertain that an accessable bay exists.	Disabled bay next to newsagent across from trangular island on Bridge Street.	1	11	4	€240
303556	172948	An accessible bay was found on the day of the audit, it could not be determined if this was a local authority provided bay. This particular bay had no high level signage and would be difficult for persons without prior local knowledge to know that it existed. Assuming that this is dedicated to disabled parking, proper markings need to be put in place as well as a dropped kerb. Refer to section 5.4.2 of NDA "Building for Everyone".	Outside of health centre along Bridge Street.	1	23	2	€1,080
	REF: 10.7	QUESTION: Is there a sufficient number of accessible pa per 25-50 spaces, 5 spaces per 50-100 stan		e per 25 s	standard spaces,	3 spaces	Y/N: Yes